



NOTE: AUXILIARY BOLT STRIKE ALWAYS ABOVE STRIKE ROLLER

268 RIM STRIKE

IR VON DUPRIN ②

NOTE: SEE MASTER SHEET NO. 10001 FOR SUGGESTED REINFORCING

TEMPLATE NUMBER:

30011_2

DATE:
7-28-98