



IT IS RECOMMENDED THE MOUNTING HOLES BE PREPARED IN THE FIELD

210 DT TRIM



NOTES: SEE MASTER SHEET #10001 FOR SUGGESTED REINFORCING

TEMPLATE NUMBER: 20015\_0

DATE: 5-19-99