



NOTE: IT IS RECOMMENDED THE MOUNTING HOLES BE PREPARED IN THE FIELD

FOR CUTOUTS ON INSIDE FACE OF DOOR SEE DEVICE TEMPLATE.

230 EO TRIM



NOTES: SEE MASTER SHEET NO. 10001 FOR SUGGESTED REINFORCING

TEMPLATE NUMBER:

20035\_1

DATE:

8-18-98