



550 DT TRIM FOR
94/9547 VERTICAL & 94/9575 MORT



NOTES: SEE MASTER SHEET #10001 FOR SUGGESTED REINFORCING

TEMPLATE NUMBER: 20031_0

DATE: 6-15-00