



FOR CUTOUTS ON INSIDE FACE OF DOOR SEE DEVICE TEMPLATE.

NOTE: IT IS RECOMMENDED THE MOUNTING HOLES BE PREPARED IN THE FIELD

230 DT TRIM



NOTES: SEE MASTER SHEET NO. 10001 FOR SUGGESTED REINFORCING

TEMPLATE NUMBER: 20036\_1

DATE: 8-18-98