



NOTE:
 1. THIS STRIKE IS NOT HANDED. LATCH BOLT
 OPENING IS OFFSET IN THE SAME DIRECTION
 FOR "LHR" AND "RHR" APPLICATION.

283 STRIKE APPLICATION FOR 98/9947
 -WDC, 33/3547-WDC & 33/3547A-WDC (2)



NOTE: SEE MASTER SHEET NO. 10001 FOR SUGGESTED REINFORCING.

TEMPLATE NUMBER: W30230_2

DATE: 06-26-03